

FIG. 1

2/8




FIG.2




FIG.3




FIG.4




FIG. 5




FIG. 6A

FIG. 6B

FIG. 6C

FIG. 6D

FIG. 6E

FIG. 6F

FIG. 6G

FIG. 6H

FIG. 7A




FIG. 7B




FIG. 7C





FIG. 7D



PHASE SHIFT	$-\pi$		$-\pi/2$		0		$\pi/2$		$\pi$
S7I	-	-	0	+	+	+	0	-	-
S7Q	0	-	-	-	0	+	+	+	0
CONTROL DIRECTION	0	+	0	-	0	+	0	-	0

FIG.8